

Suitable for gel coats and

painted finishes

2K Polyurethane Finishes

2K Acrylic Finishes

Waterborne Finishes

Polyester Finishes

PAINT TYPES


Profile Premium System Process Chart

High gloss polishing guide: Industrial coatings



SANDING










Identify surface defects to be removed



Sand using P1200 abrasive discs

Step 1: COMPOUNDING





Profile Premium Liquid Compound



Code **PRL101**

Applicators	
G Mop 6" Lambs Wool Pad	
G Mop 8" Lambs Wool Pad	
G Mop 6" High Cut Foam	
G Mop 8" High Cut Foam	



Attach a G Mop Lambs Wool Pad or High Cut Foam to a polisher

1500 - 1800rpm

Compound the

1500 - 1800rpm

surface at



Shake bottle well before use



Once flatting marks are removed, wipe clean with a Finishing Cloth

Step 2: FINISHING (optional)





Code

GML601 GML801

GMC618 GMC818

Dispense a small

product on to the

surface or pad

quantity of

Profile Finish Finishing Compound





Product 1 litre

Code **PRF101**

Applicators G Mop 6" Finishing Foam

G Mop 8" Finishing Foam





Attach a G Mop Finishing Foam to a polisher



Shake bottle well before use



Dispense a small quantity of product on to the surface or pad



Compound the surface at a low speed 800 - 1100rpm



Once the desired







